


I PD3WHTY&I PD3BLKZ



Correct Set up Instruction

step 1



Note :
Counterclockwise rotation
the tool fastening screw.


step 2





A=1PC

Error Set up Instruction

step 1




step 2





M5X20

B=4PCS




C=2PCS


step 3




E=1PC



D=2PCS



TOOL=1PCS



M5X25

F=4PCS