


TV12B27

Gas-Strut Flexi Full Motion Wall Mount





Fits most display size:17"-27"
Max Load:4.4-15 lbs(2-7kg)
VESA:75x75-100x100mm

Hand tools required


- Công cụ bắt buớc
- Narzędzia do montažu
- เครื่องมือติดตั้งใช้
- Tools used
- ツールの使用
- 도구의 사용
- Der Einsatz von Werkzeugen
- Использование инструментов
- El uso de herramientas
- L'utilisation des outils
- Het gebruik van instrumenten
- L'uso di strumenti
- استخدام الأدوات
- A utilização de ferramentas
- Penggunaan alat-alat
- 使用工具

Hand tools required for installation




- | | |
|---------------------------|--------------------------|
| A — (M4×12)-4pcs | E — (Φ10×50)-2pcs |
| B — (M5×12)-4pcs | F — (M5)-1pcs |
| C — (10-12mm)-1pcs | |
| D — (M6×60)-2pcs | |
| | (Φ16×Φ6.2×1.5)-2pcs |


A. Positioning & installation of flexi mount(2 men)




B1.Install flexi mount onto masonry or concrete (2 men)




B2.Install flexi mount onto wood stud (2 men)




C.Display installation



D. Cables and wires routing



E.Setting static position



F.Setting tilt angles positions

